

1.933
E-67 Sm 63UNITED STATES DEPARTMENT OF AGRICULTURE
Rural Electrification Administration
Washington 25, D. C.TECHNICAL STANDARDS COMMITTEES
Month of February 1950

The following is a summary of the changes in the "List of Materials Acceptable For Use on REA-Financed Systems" resulting from decisions of the Technical Standards Committees during the month of February 1950:

1. Page p-2a - Connectors, ACSR to ACSR

Add Joslyn number J3016 to replace numbers J3044 and J3055 for No. 2 and No. 4 ACSR over armor rods.

Add Reliable number 744AL for 4/0 and 3/0 bare conductors.

2. Page p-2b - Connectors, ACSR to No. 4A Copperweld Copper

Add Joslyn number J3216 for 4/0 and 3/0 bare conductors.

Add Joslyn number J3216 to replace number J3144 for No. 2 and No. 4 ACSR over armor rods.

3. Page p-2c - Connectors ACSR to 4 & 6 Copper, or 6A, 8A, 9½D, 3#12 CWC.

Add Joslyn number J3216 for 4/0 and 3/0 bare conductors.

Add Joslyn number J3216 to replace number J3144 for No. 2 ACSR over armor rods.

4. Page p-3c - Connectors, Steel and Amerductor

Revise Joslyn listing to read as follows:

Steel*	4	6	8	
Amerductor	4	6	8	8X, 9X, 10, 12

Joslyn

To ACSR**	1/0	J3044	J3044	J3044	J3044
	2	J3044	J3016	J3016	J3016
	4	J3055	J3055	J3055	J3055
To Guy Strand		J3031	J3031	J3031	J3031
1/4" to 7/16"					

*Amersteel, Ruralductor, Crapo

**Over Armor Rods

Note: These connectors are to be used for replacement purposes only.

2-Technical Standards Committees

Materials List Changes - Month of February 1950

5. Page z-1 - Anchors, Expanding and Plate

Add Chance number 6870 on page "z-1" for 2500 pound service only.

6. Page z-5 - Anchors, Cone

Add Chance numbers 8-S, 10-S, and 12-S to replace numbers 8, 10, and 12, respectively.

7. Page ae - Lightning Arresters, Distribution

Add General Electric model No. 9LA17C35 as follows:

<u>Manufacturer</u>	<u>Type</u>	<u>Mounting</u>	<u>Catalog No.</u>
Gen. Electric	Hi-stroke arrester	FR-1 automatic recloser tank	9LA17C35

8. Add new page as follows:

Page az - Pole numbers and letters, metal
(See Dwgs. M52-1R, M52-2R, and M52-3R)

	<u>M52-1</u>	<u>M52-2</u>	<u>M52-3</u>
<u>Manufacturer</u>		<u>Catalog Numbers</u>	
Premax Products	1521	1522	1523

9. Page cg-2 - Switches, pole top, air-break, group-operated

Delete Line Material catalog numbers covering two and three insulator switches and replace by type designations as follows:

<u>Manufacturer</u>	<u>Types</u>	
	2-Insulator	3-Insulator
Line Material	T2S	T3S

10. Page ct - Plate, double arming

Add Hubbard number 6819 as follows:

<u>Manufacturer</u>	<u>4" x 1/4" x 17"</u>
Hubbard	6819

3-Technical Standards Committees
Materials List Changes - Month of February 1950

11. Page cy - Sleeve, splicing, compression type

Add Reliable number 4ALx6CU as follows:

#4 ACSR to #6 Copper

Manufacturer

Catalog Number

Reliable

4ALx6CU

12. Page da - Bracket, insulated

Add Locke number 0327 under the heading "Bracket without insulator."

13. Add new page as follows:

Page du - Extension Links

(1-3/4" x 3/8", 20" between centers of holes)

Manufacturer

Catalog Number

Joslyn

J2528

14. Page en - Double support plate

Add Utilities Service number 4070.

U.S. DEPT. OF AGRICULTURE
MAY 12 1950
LIBRARY